

Stock #: 119733

Unit #: Q78386 CNA

Customer: RAQUEL BUSH

Lot #: N 0142

POST CONDITION REPORT



Date: 6/24/13 5:19 PM

Seller: REMARKETING SERVICES

#L6105

Phone/Fax: (716) 564-4000/(716)

564-4040

Sale Date: 06/25/2013

Year	Make	Model	Body Type	Doors	VIN			
2005	LEXUS	ES 330 BAS	SEDAN 4 DOOR	4	JTHBA30GX55098287			
Drive	Ext Color	Int Color	Int Material	EOT	Lic. Plate	State	# of	Expires
F	Black	Gray	Leather					
Odometer		Engine		Transmission		Sound	Roof	Airbags
283092	Digital	6-Cyl. 3.3L	Gas	Auto		w/CD	Sun	Dual

- **Accessories:**Ignition keys (1), Trunk keys (0)
- **Interior:**Rear defroster, Power roof, Power locks, Memory seats, Steering wheel audio controls, Power mirrors, A/c seats, Dual air, Heated seats (DRIVER & PASSENGER), Cruise control, Power windows, Tilt wheel, Steering wheel controls, Power seats
- **Exterior:**Alloy wheels, Fog lights
- **Equipment:**Antilock brake system, Side air bags, Power brakes, Power steering, Air conditioner
- **Electronics:**Navigation system, Cd player

Notification:

Driveable: Yes

Arrival: 06/21/2013

Visual Frame Damage: No

Visual: 06/24/2013

General Condition: 2.0

Body: 06/24/2013

Mechanical: 06/24/2013

CR Writer: JH

CR Completed: 06/24/2013

Book Value: \$ 5200

Tires:	Left	Right
Front	06/32in Other 17	07/32in Other 17
Rear	07/32in Other 17	09/32in Other 17
Spare		



Announcements:

Notes:

- 16" WHEELS
- 1/2 TANK
- TD/LS


Inspection Date	Description	Material Estimate	Labor Hours	Labor Estimate	Paint Hours	Paint Estimate	Sublet Estimate
06/24/2013	Suspension noise -Tires	0.00	0.00	0.00	0.00	0.00	0.00
06/24/2013	Power steering pump leak	0.00	0.00	0.00	0.00	0.00	400.00
06/24/2013	Engine seals leak -Rear main	0.00	0.00	0.00	0.00	0.00	500.00
06/24/2013	Valve covers leak	0.00	0.00	0.00	0.00	0.00	100.00
06/24/2013	Front bumper broken	0.00	0.00	0.00	0.00	0.00	200.00
06/24/2013	Headlights oxidized	0.00	0.00	0.00	0.00	0.00	40.00
06/24/2013	Hood hail dmg heavy	0.00	0.00	0.00	0.00	0.00	0.00
06/24/2013	Lf door panel torn	0.00	0.00	0.00	0.00	0.00	100.00
06/24/2013	Lf seat worn	0.00	0.00	0.00	0.00	0.00	50.00
06/24/2013	Rf seat worn	0.00	0.00	0.00	0.00	0.00	50.00
	Radio controls inop						

06/24/2013	-Display	0.00	0.00	0.00	0.00	0.00	400.00	
06/24/2013	Steering wheel worn	0.00	0.00	0.00	0.00	0.00	50.00	
06/24/2013	Carpet stained	0.00	0.00	0.00	0.00	0.00	0.00	
06/24/2013	Warning - engine on	0.00	0.00	0.00	0.00	0.00	0.00	
06/24/2013	Dash panel unattached	0.00	0.00	0.00	0.00	0.00	150.00	
06/24/2013	Headliner stained	0.00	0.00	0.00	0.00	0.00	50.00	
06/24/2013	L a pillar ding	0.00	0.00	0.00	0.00	0.00	100.00	
06/24/2013	L b pillar mult dents/paint dam	0.00	0.00	0.00	0.00	0.00	100.00	
06/24/2013	Lf door ding	0.00	0.00	0.00	0.00	0.00	50.00	
06/24/2013	Lf fender ding	0.00	0.00	0.00	0.00	0.00	50.00	
06/24/2013	Lr door ding	0.00	0.00	0.00	0.00	0.00	50.00	
06/24/2013	Lr door mult scratches/light	0.00	0.00	0.00	0.00	0.00	50.00	
06/24/2013	L fuel door mult scratches/heavy	0.00	0.00	0.00	0.00	0.00	50.00	
06/24/2013	L qtr panel ding	0.00	0.00	0.00	0.00	0.00	50.00	
06/24/2013	L qtr panel mult scratches/heavy	0.00	0.00	0.00	0.00	0.00	50.00	
06/24/2013	Rear bumper bent	0.00	0.00	0.00	0.00	0.00	100.00	
06/24/2013	Rear bumper mult scratches/heavy	0.00	0.00	0.00	0.00	0.00	100.00	
06/24/2013	Deck lid hail dmg heavy	0.00	0.00	0.00	0.00	0.00	0.00	
06/24/2013	Rf door ding	0.00	0.00	0.00	0.00	0.00	150.00	
06/24/2013	Rf door mult scratches/heavy	0.00	0.00	0.00	0.00	0.00	100.00	
06/24/2013	Rf door molding broken	0.00	0.00	0.00	0.00	0.00	100.00	
06/24/2013	Rf fender ding	0.00	0.00	0.00	0.00	0.00	50.00	
06/24/2013	Rr door ding	0.00	0.00	0.00	0.00	0.00	100.00	
06/24/2013	R qtr panel ding	0.00	0.00	0.00	0.00	0.00	100.00	
06/24/2013	Roof hail dmg heavy	0.00	0.00	0.00	0.00	0.00	0.00	
Total Estimate:		\$0.00	0.0	\$0.00	0.0	\$0.00	\$3,440.00	
Grand Total:								\$3,440.00

Charge Date	Description	Amount
06/21/2013	Pick-up charge	110.00
06/21/2013	Prepaid fees	449.00
06/21/2013	Full cleanup	65.00
Total Charges:		\$624.00



Front bumper broken



Hood hail dmg heavy



Lf door panel torn



Radio controls inop



Dash panel unattached



L b pillar mult dents/paint dam




Pic-front right



Pic-interior



Pic-odometer



Pic-rear left




Pic-rear right




Rear bumper bent



Rear bumper mult scratches/heavy



Deck lid hail dmg heavy



Rf door ding



Rf door molding broken



Roof hail dmg heavy

Rawls Auto Auction

P O BOX 3069, Leesville, SC 29070

(803) 657-5111 / (803) 657-7697

Stk:119733